OPTIMA® BlueTop SLI 4,2



Battery Model: BT SLI 4,2 Part Number: 806 252 000 888 2 Nominal Voltage: 12 volts NSN: 6140-01-475-9416 Description: High power, sealed lead acid, marine starting battery

Physical Characteristics:

Plate Design:	High purity lead-tin alloy. Wound cell configuration utilizing proprietary <i>SPIRALCELL</i> [®] technology.		
Electrolyte:	Sulfuric acid, H_2SO_4		
Case:	Polypropylene		
Color:	Case: Dark Gray Cover: "OPTIMA" Blue		
Group Size:	BCI: 34		

	Standard	Metric
Length:	10"	254 mm
Width:	6.875"	175 mm
Height:	7.813"	200 mm (height at the top of the terminals)
Weight:	38.4 lb.	17.4 kg

Terminal Configuration: SAE / BCI automotive and threaded stainless steel stud 5/16 - 18 UNC.

Performance Data:

Open Circuit Voltage (fully charged):	12.8 volts
Internal Resistance (fully charged):	0.0030 ohms
Capacity:	50 Ah (C/20)
Reserve Capacity:	BCI: 110 minutes
	(25 amp discharge, 80°F (26.7°C), to 10.5 volts cut-off)

Power:

CCA (EN -18°C): 815 amps MCA (BCI 0°C): 1000 amps

Recommended Charging:

The following charging methods are recommended to ensure a long battery life: (Always use a voltage regulated charger with voltage limits set as described below.)

Model: BT SLI 4,2

These batteries are designed for engine starting applications. They are <u>not</u> recommended or warranted for use in deep cycle applications.

OPTIMA® BlueTop SLI 4,2

Recommended Charging Information:

Alternator:	13.3 to 15.0 volts
Battery Charger: (Constant Voltage)	13.8 to 15.0 volts; 10 amps maximum; 6-12 hours approximate
Float Charge:	13.2 to 13.8 volts; 1 amp maximum current (indefinite time at lower voltages)
Rapid Recharge:	Maximum voltage 15.6 volts. No current limit as long as battery
(Constant voltage charger)	temperature remains below 50°C (125°F). Charge until current drops below 1 amp. All limits must be strictly adhered to.

Recharge Time: (example assuming 100% discharge – 10.5 volts)

Current	Approx. time to 90% charge
100 amps	35 minutes
50 amps	75 minutes
25 amps	140 minutes

Recharge time will vary according to temperature and charger characteristics. When using Constant Voltage chargers, amperage will taper down as the battery becomes recharged. When amperage drops below 1 amp, the battery will be close to a full state charge.

(All charge recommendations assume an average room temperature of 25°C, 77°F)

Always wear safety glasses when working with batteries.

Always use a voltage regulated battery charger with limits set to the above ratings. Overcharging can cause the safety valves to open and battery gases to escape, causing premature end of life. These gases are flammable! You cannot replace water in sealed batteries that have been overcharged. Any battery that becomes very hot while charging should be disconnected immediately.

Not fully charging a battery can result in poor performance and a reduction in capacity.

Shipping and Transportation Information:

OPTIMA batteries can be shipped by AIR. The battery is nonspillable and is tested according to ICAO Technical Instructions DOC. 9284-AN/905 to meet the requirements of Packing Instructions No. 806 and is classified as non-regulated by IATA Special Provision A-48 and A-67 for UN2800. Terminals must be protected from short circuit.

Manufacturing Location:

OPTIMA Batteries 17500 East 22nd Avenue Aurora, CO 80011 United States of America Phone: 303-340-7400 Fax: 303-340-7474

BCI = Battery Council International

OPTIMA Batteries Product Specifications: Model BT SLI 4,2 June 2005